

Residual risks of veneering ceramics (such as VITA LUMEX AC, VITA VM 11, VITA VM 9, VITA VM 13, VITA VMK Master and characterization materials, such as VITA AKZENT Plus and VITA INTERNO)

Possible complications and residual risks of veneering ceramics in general, and not specific to VITA materials, are:

- Peeling and loosening of the restoration, resulting in possible choking
- Marginal gaps
- Plaque deposits
- Periodontitis
- Irritation of and damage to the mucosa
- Intolerance and potential allergic reaction
- Breakage

These risks must be communicated to the patient by trained personnel (e.g., dental professionals).

002/11.2021