

Residual risks of polymer-based veneering resins (such as VITA VM LC, VITA VM CC, VITA AKZENT LC)

Possible complications and residual risks of polymer-based veneering resins in general, and not specific to VITA materials, are:

- Peeling of the restoration, resulting in possible choking
- Plaque deposits
- Irritation of the mucosa
- Intolerance and/or increased potential of allergic reaction
- Breakage

These risks must be communicated to the patient by trained personnel (e.g., dental professionals).

002/11.2021